


Scan this QR-Code to start a verification.

Use the barcode scanner attached to the system. Print this sheet and keep it next to the system.



SCAN SEQUENCE

Single-step verification: scan the QR-Code, follow the instruction on the display, then scan the QR-Code again (Start).

Two-step verification: scan the QR-Code, place the Calibration Checkerboard / Table in the scan zone, scan the QR-Code (Start), remove all objects from the displayed area, then scan the QR-Code again (Capture).